

SSP v1.7.0

Additional Usage Note

Renesas Synergy™ Platform
Synergy Software
Synergy Software Package

All information contained in these materials, including products and product specifications, represents information on the product at the time of publication and is subject to change by Renesas Electronics Corp. without notice. Please review the latest information published by Renesas Electronics Corp. through various means, including the Renesas Electronics Corp. website (<http://www.renesas.com>).

Notice

1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation or any other use of the circuits, software, and information in the design of your product or system. Renesas Electronics disclaims any and all liability for any losses and damages incurred by you or third parties arising from the use of these circuits, software, or information.
 2. Renesas Electronics hereby expressly disclaims any warranties against and liability for infringement or any other claims involving patents, copyrights, or other intellectual property rights of third parties, by or arising from the use of Renesas Electronics products or technical information described in this document, including but not limited to, the product data, drawings, charts, programs, algorithms, and application examples.
 3. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
 4. You shall not alter, modify, copy, or reverse engineer any Renesas Electronics product, whether in whole or in part. Renesas Electronics disclaims any and all liability for any losses or damages incurred by you or third parties arising from such alteration, modification, copying or reverse engineering.
 5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The intended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.
 - "Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; industrial robots; etc.
 - "High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control (traffic lights); large-scale communication equipment; key financial terminal systems; safety control equipment; etc.
- Unless expressly designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not intended or authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems; surgical implantations; etc.), or may cause serious property damage (space system; undersea repeaters; nuclear power control systems; aircraft control systems; key plant systems; military equipment; etc.). Renesas Electronics disclaims any and all liability for any damages or losses incurred by you or any third parties arising from the use of any Renesas Electronics product that is inconsistent with any Renesas Electronics data sheet, user's manual or other Renesas Electronics document.
6. When using Renesas Electronics products, refer to the latest product information (data sheets, user's manuals, application notes, "General Notes for Handling and Using Semiconductor Devices" in the reliability handbook, etc.), and ensure that usage conditions are within the ranges specified by Renesas Electronics with respect to maximum ratings, operating power supply voltage range, heat dissipation characteristics, installation, etc. Renesas Electronics disclaims any and all liability for any malfunctions, failure or accident arising out of the use of Renesas Electronics products outside of such specified ranges.
 7. Although Renesas Electronics endeavors to improve the quality and reliability of Renesas Electronics products, semiconductor products have specific characteristics, such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Unless designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not subject to radiation resistance design. You are responsible for implementing safety measures to guard against the possibility of bodily injury, injury or damage caused by fire, and/or danger to the public in the event of a failure or malfunction of Renesas Electronics products, such as safety design for hardware and software, including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult and impractical, you are responsible for evaluating the safety of the final products or systems manufactured by you.
 8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. You are responsible for carefully and sufficiently investigating applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive, and using Renesas Electronics products in compliance with all these applicable laws and regulations. Renesas Electronics disclaims any and all liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
 9. Renesas Electronics products and technologies shall not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You shall comply with any applicable export control laws and regulations promulgated and administered by the governments of any countries asserting jurisdiction over the parties or transactions.
 10. It is the responsibility of the buyer or distributor of Renesas Electronics products, or any other party who distributes, disposes of, or otherwise sells or transfers the product to a third party, to notify such third party in advance of the contents and conditions set forth in this document.
 11. This document shall not be reprinted, reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
 12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products.

(Note1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its directly or indirectly controlled subsidiaries.

(Note2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

(Rev.4.0-1 November 2017)

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Renesas Synergy™ Platform

SSP v1.7.0 Additional Usage Note

Contents

1. Introduction.....	2
2. Release Information.....	2
3. SSP v1.7.0 Additional Usage Note	2
3.1 BSP for SSP Supported Platforms	2
3.2 Crypto/r_sce	2
3.3 GUIX Integration.....	3
3.4 ISDE User Experience Improvement	3
3.5 LevelX Records	3
3.6 MCU Implementation/ SW Architecture.....	3
3.7 NetX.....	3
3.8 nxd_tls_secure	4
3.9 r_adc.....	4
3.10 r_ctsu.....	4
3.11 r_sci_spi	5
3.12 sf_audio_playback_hw_dac	5
3.13 sf_ble	5
3.14 sf_cellular	6
3.15 sf_ble	6
3.16 sf_el_fx	6
3.17 sf_el_lx_nor	6
3.18 sf_el_nx	7
3.19 sf_el_ux	7
3.20 sf_el_ux_comms_v2.....	8
3.21 sf_touch_ctsu	8
3.22 sf_touch_ctsu_button	8
3.23 sf_WiFi.....	9
3.24 SSP IAR Support.....	9
3.25 SSP XMLs for ISDE.....	10
3.26 Synergy Software Configurator	10
3.27 Synergy Tools.....	10
3.28 tes.....	11
3.29 Tools Development.....	11
3.30 USBX.....	11
4. Additional Technical Notes	12

5. Revision History.....	14
--------------------------	----

1. Introduction

This document describes additional usage notes for **Synergy Software Package (SSP) version 1.7.0**.

2. Release Information

SSP Release Version	v1.7.0
Release Date	Sep 10, 2019

The intended audience for this release is Renesas Synergy™ customers, prospective customers, partners, and support staff. This document lists additional information on SSP v1.7.0 usage. See the *SSP v1.7.0 Release Note* for enhancements, bug fixes, and known issues that were identified since the last release for SSP v1.6.0.

3. SSP v1.7.0 Additional Usage Note

3.1 BSP for SSP Supported Platforms

Issue ID: 2625

Unaligned access across the memory map boundary 0x20000000 (between SRAMHS and SRAM0) results in a data read/write failure due to the Synergy hardware restriction. However, user applications might cause an unaligned access across the boundary, since linker script files for S7 or S5 MCU parts define the single 'RAM' section across SRAMHS and SRAM0. For details on this hardware restriction, see the *Arm® Cortex®-M4 Technical Reference Manual*, section 3.4.3

http://infocenter.arm.com/help/topic/com.arm.doc.100166_0001_00_en/arm_cortexm4_processor_trm_100166_0001_00_en.pdf.

Applies to: S7 and S5 MCU Series

Workaround: Users need to modify their linker script manually to ensure that objects do not cross the memory map boundary, 0x20000000.

Issue ID: 10664

If a user is using the trace buffer for debugging and has data stored in the RAM at addresses above 0x20004000, that data is overwritten by the trace buffer when debugging.

Applies to: S1JA and S128 MCU Groups

Workaround: The S128 linker script currently allocates 1K for the trace buffer at 0x20000000. This allocation could be removed, freeing up the 1K incorrectly reserved for the trace buffer. Using the e² studio trace buffer function will store 1K of the trace buffer data beginning at 0x20004000. Therefore, 1K of RAM must not be used by the application if the trace buffer is to be used for debugging.

3.2 Crypto/r_sce

Issue ID: 11147

Only data input lengths that are multiples of the AES block size are supported for AES encryption/decryption APIs for XTS chaining mode.

Applies to: S7, S5, and S3 MCU Series

Workaround: None

Issue ID: 15261

The key generation time for 1024-bit RSA varies from 170 milliseconds to 1.2 seconds, while for 2048-bit RSA, it varies from 1.65 seconds to 10 seconds. This results in a noticeable delay during RSA 2048-bit key generation, at times.

Applies to: S5 and S7 MCU Series

Workaround: None

3.3 GUIX Integration

Issue ID: 14456

Build warnings are being observed when compiling `gx_src` code with GCC 7.2.1.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: None

3.4 ISDE User Experience Improvement

Issue ID: 12908

A multiple symbol definition error may occur during linkage if an X-Ware library component and the corresponding source component such as `ux` and `ux_src` are included. If this occurs, remove the library such as `libux.a` from the list of libraries used by the linker.

For GCC, this is in the Cross ARM C Linker > Libraries section of the C/C++ Build > Settings in the project Properties.

For IAR, this is in the IAR Linker for ARM > Library section of the C/C++ Build > Settings in the project Properties.

Module Names: `ux` (USBX), `tx` (ThreadX), `nx` (NetX), `nxd` (NetX Duo), `fx` (FileX), `gx` (GUIX), `ux_host_class_XXX` (USBX Host Classes), `ux_device_class_XXX` (USBX Device Classes).

Applies to: All supported Synergy MCU Groups

Issue ID: 13854

When debugging a project with a large number of threads (for example, 150 threads), with the RTOS Resource view open, e² studio might hang and become unresponsive.

Applies to: All MCUs

Workaround: Make the RTOS Resource View small and expand it once the Debug Tree view has finished updating.

3.5 LevelX Records

Issue ID: 14455

Build warnings are observed when compiling `lx_nand_src` with GCC 7.2.1.

Applies to: S3, S5, and S7 MCU Series

Workaround: None

3.6 MCU Implementation/ SW Architecture

Issue ID: 10864

The pin configuration tab in the configurator cannot be used to configure the opamp or analog comparators for every use case.

Applies to: S7G2, S5D9, S5D5, S5D3, S3A7, S3A3, S128, and S124 MCU Groups

Workaround: Configure the pins manually in the user-defined code.

3.7 NetX

Issue ID: 7745

The NetX/NetX Duo FTP Client requires FileX in Stack configuration. Due to dependencies, FileX cannot be removed from the configurator while using the FTP_Client application.

Applies to: S7G2, S5D9, and S5D5 MCU Groups

Workaround: None

Issue ID: 11994

The NetX/Duo FTP server does not support passive data transfer mode. Hence, only active mode FTP can be currently used.

Applies to: S7G2, S5D9, S5D5, and S5D3 MCU Groups

Workaround: None

Issue ID: 14293

Warnings will be observed on compiling nxd applications with GCC7.

Applies to: S7, S5, and S3 Series MCUs

Workaround: None

Issue ID: 15218

When multiple network interfaces are used in the application, since the IP Driver interface structure member is not initialized properly in the IP's helper thread function, this causes bus fault and the application goes into default handler for compiler optimization of -O0, -O2, and -O3.

Applies to: S7G2, S5D9, S5D5, and S5D3 MCUs

Workaround: Use compiler optimization -O1, -Og, and -Os during multiple network interfaces.

3.8 nxd_tls_secure

Issue ID: 15051

Warnings will be observed on compiling nxd applications with GCC7.

Applies to: S7 and S5 MCU Series

Workaround: None

3.9 r_adc

Issue ID: 14707

The S7G2, S5D9, and S5D3 MCUs have features for setting the Programmable Gain Amplifier (PGA) for single inputs and differential inputs with multiple levels of gain setting for Amplifier_0, Amplifier_1, and Amplifier_2. This feature is not supported in the existing r_adc driver. Currently, this feature is disabled, and no options are provided in the configuration parameter properties to set the gain level.

Applies to: S7G2, S5D9, and S5D3 MCU Groups

Workaround: None

3.10 r_ctsu

Issue ID: 6927

R_CTSU_Update_Parameters() returns error. Not all return codes are described in the function header. Some return codes are as follows:

SSP_ERR_NOT_OPEN when mode is set to CTSU_MODE_UNCONFIGURED

SSP_ERR_IN_USE, when the Measurement Status Counter is set to non-zero value, or the CTSU Data Transfer Status flag is set

SSP_ERR_CTSU_RC_OVERFLOW, when CTSUROVF flag is set

SSP_ERR_CTSU_SC_OVERFLOW, when CTSUSOVF flag is set

SSP_ERR_CTSU_ICOMP, when TSCAP Voltage Error Monitor flag is set.

Applies to: All supported Synergy MCU Groups

Workaround: In cases where the returned error code is not described in the function header, see the return code description in the `ssp_common_api.h` file.

Issue ID: 6928

If the application calls `R_CTSU_Read()` while the driver is in an uninitialized state, then the documented return code is `SSP_SUCCESS`, but the actual return code is `SSP_ERR_NOT_OPEN`. When calling `R_CTSU_Read()` while the driver is uninitialized, the application should expect a return code of `SSP_ERR_NOT_OPEN`.

The `R_CTSU_Read()` function is not sufficiently tested with the `CTSU_READ_FILTERED_REF_ICO_VALUES_SEL` and `CTSU_READ_FILTERED_REF_ICO_VALUES_ALL` options.

Applies to: All supported MCU Groups

Workaround: None

Issue ID: 6929

Auto-calibration, auto-scan, and auto-drift compensation features are not available in the `r_ctsu` driver.

Applies to: All MCUs

Workaround: None

Issue ID: 6931

Parameter checking for NULL parameters is not implemented. Passing in a NULL parameter to the `r_ctsu` API will result in undefined system operation.

Applies to: S7G2, S5D9, S5D5, S3A7, S128, and S124 MCU Groups

Workaround: When using this driver, make sure that the control structure passed to the `r_ctsu` API is not NULL.

3.11 r_sci_spi

Issue ID: 10962

Each MCU supports a different range of bit rates and this depends on the speed of the clock provided to the SCI-SPI peripheral. For the maximum supported bit rate for a particular MCU, see the corresponding MCU User's Manual.

Applies to: All MCUs

Workaround: None

3.12 sf_audio_playback_hw_dac

Issue ID: 9308

`sf_audio_playback` is not tested with the DMAC module as a transfer driver.

Applies to: All boards except S1JA, S128, and S124 boards

Workaround: `sf_audio_playback` module can use DTC module as a transfer driver, instead of DMAC.

3.13 sf_ble

Issue ID: 9256

The projects using RL78G1D framework will see compilation warnings. All the warnings are in the 3rd party RL78G1D driver code and will not have impact on user applications. The RL78G1D framework file does not have any warnings.

Applies to: RL78G1D on all MCUs

Workaround: None

3.14 sf_cellular

Issue ID: 9475

Applications using the cellular framework will not be able to upgrade module firmware over the air (FOTA) since FOTA is not supported by the cellular framework.

Applies to: Cellular framework CAT3 and CAT1 implementation on all MCUs

Workaround: None

3.15 sf_ble

Issue ID: 9225

HID profile client mode is not supported by RL78G1D. As a result, the BLE framework implementation of the HID profile also does not support the HID profile client mode. Applications using the BLE framework for RL78G1D will not be able to use the HID profile in client mode.

Applies to: All MCUs

Workaround: None

3.16 sf_el_fx

Issue ID: 12753

The warning "control reaches end of non-void function" will be seen if code is configured to reach `fx_fault_tolerant_transaction_fail()`.

Applies to: S7, S5, and S3 MCU Series

Workaround: None

Issue ID: 14281

The FileX update rate of the system time happens depending on the macro value of `FX_UPDATE_RATE_IN_SECONDS` and `FX_UPDATE_RATE_IN_TICKS` in `fx_api.h`. There is a FileX configurator option that controls `FX_UPDATE_RATE_IN_SECONDS` value, but there is no user configurator option to control the `FX_UPDATE_RATE_IN_TICKS` value, and therefore the FileX update rate of the system time cannot be effectively controlled.

Applies to: All MCUs

Workaround: Disable Synergy builder and update `FX_UPDATE_RATE_IN_TICKS` in `fx_api.h` as required.

3.17 sf_el_ix_nor

Issue ID: 12613

Build warnings are observed when compiling `sf_el_ix_nor` with GCC.

Applies to: S7, S5, and S3 MCU Series

Workaround: None

Issue ID: 15029

1. The current `sf_el_ix_nor` framework does not have the functionality to resize the flash memory out of the total memory available.
2. Even though the DK-S7G2, DK-S3A7, ADK-S3A3, TBB-S5D5, and ADK-S3A1 boards have over 16 MB of flash memory, only 16 MB is accessible.

Applies to: All MCUs

Workaround: There is no workaround because:

1. The feature is unsupported.
2. The current QSPI BSP is hard-coded to 3-byte addressing.

3.18 sf_el_nx

Issue ID: 7513

The current sf_el_nx (NetX Port driver) is hard-coded to use the RMI interface which is for a Micrel Ethernet PHY chip mounted on Renesas kits but does not support other PHY chips or MII interfaces. The customer defines an Ethernet PHY chip driver when using a different PHY chip than the one mounted on Renesas kits, or when using a PHY chip with a MII interface.

Workaround: There is no plan to provide support for additional Ethernet PHY chip drivers included in SSP; users are required to create their own PHY chip driver.

To create a PHY chip driver, users can use the sf_el_nx (NetX Port) module under **/ssp/src/framework/sf_el_nx/** as a template and modify it for the target Ethernet PHY chip. Source files under sf_el_nx are in plain text; you can copy the file to other directories, such as **/src/** directory, and exclude the original sf_el_nx module from being built to avoid 'multiple definition' compile-error.

The following steps give high-level guidance to work around the issue:

1. Copy the directory **/ssp/src/framework/sf_el_nx/** including all the files under the directory to **/src/**.
2. Exclude original sf_el_nx module in SSP from your build. Right click on the directory **/ssp/src/framework/sf_el_nx/** and select '**Exclude from build...**'. Then click the '**Select All**' button.
3. Modify **/src/sf_el_nx/nx_hw_init.c**. Modify nx_synergy_ethernet_init() as indicated below to select the MII interface. Change IOPORT_ETHERNET_MODE_RMII to **IOPORT_ETHERNET_MODE_MII**.
g_ioport_on_ioport.pinEthernetModeCfg(IOPORT_ETHERNET_CHANNEL_n,
IOPORT_ETHERNET_MODE_RMII);
4. Modify **/src/sf_el_nx/phy/ether_phy.c** and **ether_phy.h**. Modify these files to match to your Ethernet PHY chip.
5. Be sure to select MII pins under the '**Pins**' tab in the Synergy Configurator. Check the pin configuration setting, **Peripherals > Connectivity:ETHERC**.

Notes: 1. Source files under **/ssp/src/framework/sf_el_nx/** are overwritten by the tool when building a project. Be sure to copy the files before editing.

2. To exclude files from building, right-click on the files and select **Exclude from build** (as is the case for e² studio).

3.19 sf_el_ux

Issue ID: 8574

The current sf_el_ux HCD driver does not enable the Double Buffer feature for Bulk OUT PIPEs, which is supported by the USB hardware. Therefore, USB data throughput for Data Write through a Bulk OUT PIPE will be less than the value for Double Buffer-Enabled. This issue is only for Data Write (Bulk OUT). Double buffering is supported for Data Read (Bulk IN).

Applies to: S7, S5, and S3 MCU Series

Workaround: None

Issue ID: 13528

In USBX Device CDC class, in blocking mode, write/read calls made to the sf_el_ux DCD driver do not support the timeout feature, and this may result in indefinite waiting for the host transfer to get completed.

Note: **Option 1:** In order to use the non-blocking or callback mode in USBX CDC device class, call the `ux_device_class_cdc_acm_ioctl()` API in the application to use transmission with callback. See the latest *USBX Device Stack User Guide* for more information on Device class APIs.

Option 2: Call the `ux_device_stack_transfer_abort()` API from other threads in the application to abort the pending transfer requests.

Applies to: All MCUs

Workaround: None

Issue ID: 14447

DMA is not supported for composite device class due to which the composite device fails to work when DMA transfer mode is enabled.

Applies to: All MCUs

Workaround: Use CPU transfer mode instead of DMA

Issue ID: 15370

`ux_host_class_printer_status_get` function does not return the status of the printer, if the length sent by the device (printer) is 1 byte.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: None

3.20 `sf_el_ux_comms_v2`

Issue ID: 15552

In USBX CDC Communications Framework, initialization fails when the DTC transfer driver is used.

Applies to: All MCUs

Workaround: Use the DMA transfer driver instead of the DTC transfer driver, or do not use any transfer driver (default)

3.21 `sf_touch_ctsu`

Issue ID: 6858

When channel is set to NULL, the `SF_TOUCH_CTSU_Read()` returns `SSP_ERR_INTERNAL`.

Return values from the ThreadX API calls are not checked in the framework, which can lead to functional issues in the framework when ThreadX APIs return errors. The framework may not work as expected in such cases, since errors are not handled.

With valid callback and context, if `callback_index` is set to `SF_TOUCH_CTSU_CFG_MAX_WIDGET_TYPES (= 3)`, `SF_TOUCH_CTSU_Open()` returns `SSP_ERR_OUT_OF_MEMORY`.

Applies to: All MCUs

Workaround: None

Issue ID: 6859

`SF_TOUCH_CTSU_Read()` returns the error value `SSP_ERR_INTERNAL` if the semaphore **get** or **put** is not successful.

Applies to: All MCUs

Workaround: None

3.22 `sf_touch_ctsu_button`

Issue ID: 6882

1. Valid range for `button_count` is 0 to less than `SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12)`.
2. For `button_count` values outside the range, `SF_TOUCH_CTSU_Button_Open()` returns error `SSP_ERR_ASSERTION`.

Applies to: All MCUs

Workaround: None

Issue ID: 6883

For `button_count` values outside the range, `SF_TOUCH_CTSU_Button_Open()` returns the error `SSP_ERR_ASSERTION`, and buttons outside the range cannot be operated.

Applies to: All MCUs

Workaround: The `button_count` values must be set to value 0 to less than `SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12)`.

Issue ID: 9661

`SF_TOUCH_CTSU_BUTTON` module is not built for the S5D5_proto board. The build configuration needs to be updated.

Applies to: S5D5 MCU Group

Workaround: Add S5D5_proto board in the `SF_TOUCH_CTSU_BUTTON` build XML

Issue ID: 12742

The GT202 module supported by the WiFi Framework is affected by the WPA2 KRACK issue.

Applies to: GT202 module supported by the WiFi Framework

Workaround: None

3.23 sf_WiFi

Issue ID: 8394

The projects using GT202 framework will see compilation warnings. All the warnings are in the 3rd party GT202 driver code. The GT202 framework files do not have any warnings. The warnings should not impact the user applications.

Applies to: WiFi Framework for GT202 on DK-S7G2, DK-S3A7, PK-S5D9, TB-S5D5, TB-S3A6 (only socket), ADK-S3A3 MCUs

Workaround: None

Issue ID: 15379

Customers cannot build a project using WiFi and the NSAL layer without getting an error.

Compilation of the project will fail when you include `sf_wifi_nsal_nx` since the XML declaration section is missing an external reference definition.

Applies to: All MCUs supporting WiFi

Workaround: Update the `Renesas##Framework Services##all##sf_wifi_nsal_nx####1.6.3.xml` file with the needed change in the declaration section.

Issue ID: 14126

WiFi WPS functionality does not work with WPA security.

Applies to: WiFi Framework using GT202

Workaround: None

3.24 SSP IAR Support

Issue ID: 12972

C-RUN with bounds checking is not supported with Synergy project in EWSYN.

Applies to: All MCUs

Workaround: None

Issue ID: 15377

An error message pops up when selecting the device in Project Explorer, with the **Properties** view open. Synergy plugins have to be upgraded using the IAR Embedded workbench plugin manager to fix the error message when selecting the device with the **Properties** view open.

Applies to: All MCUs

Workaround: None

Issue ID: 14485

Library projects which use multiple or long include paths cause the compiler command line to exceed the system limit and fail to build the library.

Applies to: Projects created with IAR compiler in e² studio

Workaround: None

3.25 SSP XMLs for ISDE

Issue ID: 10695

The configurator does not warn about the limitation on the RSPI bit rate if the bit rate is less than or equal to 30 MHz.

Applies to: All MCUs

Workaround: The RSPI bit rate must be a positive integer that is less than or equal to 30 MHz or PCLK/2, whichever is the smaller value.

3.26 Synergy Software Configurator

Issue ID: 7665

When using the Synergy Software Configurator in e² studio/SSC, if you rename a thread on the Threads tab and generate code, a new `thread_entry.c` file is created with template content, and the old `thread_entry.c` file remains in the project. If you have edited the `thread_entry.c` file, your changes are not moved to the new file. The old file remains in the project. It will not be called; it causes a build error if not removed from the project manually.

Applies to: All MCUs

Workaround: Manually move any edits (if made) from the old `thread_entry.c` file to the new `thread_entry.c` file, then manually delete the old `thread_entry.c` file from your project.

3.27 Synergy Tools

Issue ID: 14436

Some of the old projects with customized stacks might fail after migrating to e² studio v7.3 because the default modules gets repopulated in the stack.

Applies to: All MCUs

Workaround: The user explicitly needs to delete the modules that are repopulated after migration.

Issue ID: 14636

The build fails when GCC 4.9 is used for the S1JA device as the S1JA device is not supported by GCC compiler version 4.9.

Applies to: S1JA MCU Group

Workaround: Do not select the GCC 4.9 toolchain for the S1JA device.

Issue ID: 15093

Using the option “Rename and import existing C/C++ project” causes intermittent failure in importing the project, and gives an error message.

Applies to: All MCUs

Workaround: None

Issue ID: 15104

e² studio v7.3.0 is sensitive to the casing of linker script file names. This is experienced only in the projects created with the previous version of e² studio where the linker script names do not exactly match in casing. In this case, the user would experience a build error saying that the linker script is not found.

Applies to: All MCUs

Workaround: If the build is failing with .ld not found error, go to the linker configuration in e² studio project properties and delete the linker script entry.

Issue ID: 15330

The project that has been created with SSP versions prior to SSP v1.6.3 and edited to remove default lower level module fails to build when migrating to SSP v1.6.3.

Applies to: Projects created in earlier versions that have been edited by removing the default lower level module in thread stacks.

Workaround: Open the threads tab before building the project.

Issue ID: 15339

Default property value of the IP address does not get picked up for existing projects after changes to the pack. Opening existing projects shows the previously saved value instead of the default value from the pack.

Applies to: Applies to projects only when using the packs with the change for IP address

Workaround: None

3.28 tes

Issue ID: 14095

The rendering of concave polygons is not supported when D/AVE 2D drawing engine is enabled.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: Disable D/AVE 2D drawing engine to render concave polygons.

3.29 Tools Development

Issue ID: 15202

When TraceX standalone installer is used, TraceX fails to launch and gives a license error when the existing TraceX installation is overwritten by reinstalling TraceX.

Applies to: All MCUs

Workaround: Uninstall existing TraceX application and install it again

3.30 USBX

Issue ID: 6470

USBX Host Class Prolific (ux_host_class_prolific) is currently included in the SSP package as an experimental module but is yet to be tested, so the functionality is not guaranteed.

Applies to: All applicable MCUs

Workaround: Not applicable

Issue ID: 8505

Users need to set 'requested_length' of the USBX Device CDC API, `ux_device_class_cdc_acm_read` large enough compared to the expected reception data length. If the length of the reception data from a USB host is larger than the 'requested_length,' the API returns `UX_SUCCESS` but the reception data will not be stored in a user buffer and the actual length is set to '0'.

Applies to: All MCU Groups

Workaround: Set 'requested_length' of the USBX Device CDC API, `ux_device_class_cdc_acm_read` large enough compared to the expected reception data length.

Issue ID: 8647

The USB throughput for file read/write operation with USBX Device Class Mass Storage is not consistent and may vary for every measurement time.

Applies to: All MCU Groups

Workaround: None

Issue ID: 10027

USBX Device Class HID does not support Interrupt-Out endpoint. The use of Interrupt-Out endpoint is optional in the USB HID specification. It would not often be the case in embedded applications, but Synergy customers may require the feature for their production.

Applies to: All MCUs

Workaround: Ask Synergy customer support for a custom HID class example that enables Interrupt-In and Interrupt-Out endpoints.

Issue ID: 14100

Warnings for "this statement may fall through" will be observed when compiling the USBX Device class source code.

Applies to: All MCUs

Workaround: None

4. Additional Technical Notes

- Subscribe to the Synergy Technical Bulletin Board to receive the latest technical news and notifications about new features, known issues, workarounds, and release announcements. To subscribe, visit http://renesasrulz.com/synergy/synergy_tech_notes/f/214.aspx. Sign in to Renesas Rulz, and press **Email Subscribe to this forum.**
- Additional technical information, including informative papers and articles on SSP and Synergy can be found at Synergy Knowledge Base, www.renasssynergy.com/knowledgebase.

Website and Support

Visit the following vanity URLs to learn about key elements of the Synergy Platform, download components and related documentation, and get support.

Synergy Software	www.renesas.com/synergy/software
Synergy Software Package	www.renesas.com/synergy/ssp
Software add-ons	www.renesas.com/synergy/addons
Software glossary	www.renesas.com/synergy/softwareglossary
Development tools	www.renesas.com/synergy/tools
Synergy Hardware	www.renesas.com/synergy/hardware
Microcontrollers	www.renesas.com/synergy/mcus
MCU glossary	www.renesas.com/synergy/mcuglossary
Parametric search	www.renesas.com/synergy/parametric
Kits	www.renesas.com/synergy/kits
Synergy Solutions Gallery	www.renesas.com/synergy/solutionsgallery
Partner projects	www.renesas.com/synergy/partnerprojects
Application projects	www.renesas.com/synergy/applicationprojects
Self-service support resources:	
Documentation	www.renesas.com/synergy/docs
Knowledgebase	www.renesas.com/synergy/knowledgebase
Forums	www.renesas.com/synergy/forum
Training	www.renesas.com/synergy/training
Videos	www.renesas.com/synergy/videos
Chat and web ticket	www.renesas.com/synergy/resourcelibrary

5. Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Aug.26.19	-	Initial release
1.01	Sep.10.19	-	Second release

SSP v1.7.0 Additional Usage Note

Publication Date: Sep.10.19

Published by: Renesas Electronics Corporation

Renesas Synergy™ Platform SSP v1.7.0 Additional Usage Note