

SSP v1.7.8

Release Note

Renesas Synergy™ Platform
Synergy Software
Synergy Software Package

All information contained in these materials, including products and product specifications, represents information on the product at the time of publication and is subject to change by Renesas Electronics Corp. without notice. Please review the latest information published by Renesas Electronics Corp. through various means, including the Renesas Electronics Corp. website (<http://www.renesas.com>).

Notice

1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation or any other use of the circuits, software, and information in the design of your product or system. Renesas Electronics disclaims any and all liability for any losses and damages incurred by you or third parties arising from the use of these circuits, software, or information.
2. Renesas Electronics hereby expressly disclaims any warranties against and liability for infringement or any other claims involving patents, copyrights, or other intellectual property rights of third parties, by or arising from the use of Renesas Electronics products or technical information described in this document, including but not limited to, the product data, drawings, charts, programs, algorithms, and application examples.
3. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
4. You shall not alter, modify, copy, or reverse engineer any Renesas Electronics product, whether in whole or in part. Renesas Electronics disclaims any and all liability for any losses or damages incurred by you or third parties arising from such alteration, modification, copying or reverse engineering.
5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The intended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.

"Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; industrial robots; etc.

"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control (traffic lights); large-scale communication equipment; key financial terminal systems; safety control equipment; etc.

Unless expressly designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not intended or authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems; surgical implantations; etc.), or may cause serious property damage (space system; undersea repeaters; nuclear power control systems; aircraft control systems; key plant systems; military equipment; etc.). Renesas Electronics disclaims any and all liability for any damages or losses incurred by you or any third parties arising from the use of any Renesas Electronics product that is inconsistent with any Renesas Electronics data sheet, user's manual or other Renesas Electronics document.

6. When using Renesas Electronics products, refer to the latest product information (data sheets, user's manuals, application notes, "General Notes for Handling and Using Semiconductor Devices" in the reliability handbook, etc.), and ensure that usage conditions are within the ranges specified by Renesas Electronics with respect to maximum ratings, operating power supply voltage range, heat dissipation characteristics, installation, etc. Renesas Electronics disclaims any and all liability for any malfunctions, failure or accident arising out of the use of Renesas Electronics products outside of such specified ranges.
7. Although Renesas Electronics endeavors to improve the quality and reliability of Renesas Electronics products, semiconductor products have specific characteristics, such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Unless designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not subject to radiation resistance design. You are responsible for implementing safety measures to guard against the possibility of bodily injury, injury or damage caused by fire, and/or danger to the public in the event of a failure or malfunction of Renesas Electronics products, such as safety design for hardware and software, including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult and impractical, you are responsible for evaluating the safety of the final products or systems manufactured by you.
8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. You are responsible for carefully and sufficiently investigating applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive, and using Renesas Electronics products in compliance with all these applicable laws and regulations. Renesas Electronics disclaims any and all liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
9. Renesas Electronics products and technologies shall not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You shall comply with any applicable export control laws and regulations promulgated and administered by the governments of any countries asserting jurisdiction over the parties or transactions.
10. It is the responsibility of the buyer or distributor of Renesas Electronics products, or any other party who distributes, disposes of, or otherwise sells or transfers the product to a third party, to notify such third party in advance of the contents and conditions set forth in this document.
11. This document shall not be reprinted, reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products.

(Note1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its directly or indirectly controlled subsidiaries.

(Note2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

(Rev.4.0-1 November 2017)

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/.

Renesas Synergy™ Platform

SSP v1.7.8 Release Note
Contents

1. Introduction.....	3
2. Release Information.....	3
3. Synergy MCU Groups Supported	3
4. Software Tools and Hardware Kits Supported with this SSP Release.....	3
4.1 Version Information for Third-Party Products.....	4
5. SSP Release Package and Installation Information	5
6. Changes from SSP v1.7.5 to SSP v1.7.8.....	6
6.1 Issues Fixed in SSP v1.7.8	6
6.1.1 BSP for SSP Supported Platforms.....	6
6.1.2 GUIX Studio.....	6
6.1.3 NetX	6
6.1.4 nxd_mqtt_client	7
6.1.5 nxd_tls_secure	7
6.1.6 r_adc	8
6.1.7 r_agt	8
6.1.8 r_flash_hp.....	8
6.1.9 r_pdc	8
6.1.10 r_qspi	9
6.1.11 r_riic	9
6.1.12 sf_audio_playback.....	9
6.1.13 sf_cellular	9
6.1.14 sf_el_lx_nor.....	10
6.1.15 sf_el_nx	10
6.1.16 sf_el_tx	10
6.1.17 sf_el_ux	10
6.1.18 sf_memory_qspi_nor.....	10
6.1.19 Synergy Tools.....	11
6.1.20 USBX	11
7. Known Issues, Limitations, and Additional Usage Notes for SSP v1.7.8.....	12
7.1 BSP for SSP Supported Platforms	12
7.2 Crypto/r_sce	12
7.3 GUIX	12

7.4	ISDE User Experience	13
7.5	NetX	13
7.6	nxd_tls_secure	14
7.7	Pin Mapping Issues	14
7.8	r_agt_input_capture.....	14
7.9	r_cgc	15
7.10	r_ctsu	15
7.11	r_riic	16
7.12	r_sci_spi	16
7.13	r_sci_uart.....	17
7.14	r_sdmmc.....	17
7.15	sf_ble	17
7.16	sf_cellular	17
7.17	sf_el_gx	17
7.18	sf_el_tx	18
7.19	sf_el_ux	18
7.20	sf_i2c	19
7.21	sf_touch_ctsu	19
7.22	sf_touch_ctsu_button	19
7.23	sf_Wifi.....	20
7.24	SSP IAR Support.....	21
7.25	SSP XMLs for ISDEs.....	21
7.26	Synergy Tools.....	21
7.27	Tes	23
7.28	Tools Development.....	24
7.29	USBX	24
8.	Complete List of Modules Supported in this Release	25
8.1	BSP and Driver Modules Available in this Release.....	25
8.2	Framework Modules Supported in this Release	27
8.3	Third-Party Modules Supported in this Release.....	29
8.4	Cryptographic Functions for Each MCU Supported in this Release	30
8.5	Experimental Modules Supported in this Release	32
9.	Additional Technical Notes	32
	Revision History	34

1. Introduction

This document describes the release notes for **Synergy Software Package (SSP) version 1.7.8**.

2. Release Information

SSP Release Version	v1.7.8
Release Date	Jun 19, 2020

The intended audience for this release note is Renesas Synergy™ customers, prospective customers, partners, and support staff. This release note describes the fixed issues and known issues in SSP v1.7.8.

3. Synergy MCU Groups Supported

MCU Groups: S7G2, S5D9, S5D5, S5D3, S3A7, S3A6, S3A3, S3A1, S128, S124, and S1JA.

4. Software Tools and Hardware Kits Supported with this SSP Release

Tool	Version	Description
e ² studio	7.5.1	Software development and debugging tool. Link: www.renesas.com/synergy/tools
IAR Embedded Workbench® for Renesas Synergy™	8.23.3	Software development environment and debugging tool. Link: www.renesas.com/synergy/tools
SSC	7.5.1	Synergy Standalone Configurator. Used in combination with IAR EW for Synergy. Link: www.renesas.com/synergy/tools
GNU Arm Compiler	7.2.1 and 4.9.3	Both versions of GNU Arm® compilers are supported with SSP v1.7.8 Note: GCC 4.9.3 does not support S1JA MCU Group.
IAR Compiler	8.23.3	IAR Arm® compiler toolchain
PE-HMI1	2.0	Product Example (PE) for Human Machine Interface to evaluate Renesas Synergy™ S7G2 MCU Group
DK-S7G2	4.1	Development Kit for Renesas Synergy™ S7G2 MCU Group
SK-S7G2	3.3	Starter Kit for Renesas Synergy™ S7G2 MCU Group
PK-S5D9	1.0	Promotion Kit for Renesas Synergy™ S5D9 MCU Group
TB-S5D5	1.1	Target Board Kit for Renesas Synergy™ S5D5 MCU Group
TB-S5D3	1.0	Target Board Kit for Renesas Synergy™ S5D3 MCU Group
DK-S3A7	2.0	Development Kit for Renesas Synergy™ S3A7 MCU Group
TB-S3A6	1.0	Target Board Kit for Renesas Synergy™ S3A6 MCU Group
TB-S3A3	1.0	Target Board Kit for Renesas Synergy™ S3A3 MCU Group
TB-S3A1	1.0	Target Board Kit for Renesas Synergy™ S3A1 MCU Group
DK-S128	1.1	Development Kit for Renesas Synergy™ S128 MCU Group
DK-S124	3.1	Development Kit for Renesas Synergy™ S124 MCU Group
TB-S1JA	1.2	Target Board Kit for Renesas Synergy™ S1JA MCU Group
J-Link Software	6.34e	SEGGER J-Link® debug probe is the quasi standard for Arm® Cortex®-M based MCUs

4.1 Version Information for Third-Party Products

Component	Version in SSP v1.7.8
ThreadX®	5.9
NetX™	5.12 SP1
NetX Duo™	5.12 SP1
NetX Application bundle	5.12 SP1
NetX Duo Application bundle (MQTT, SNMP, Web HTTP)	5.12 SP1
USBX™ Host	5.9 SP1
USBX™ Device	5.9 SP1
FileX® (exFAT)	5.6 SP1 (private release 1.6.1-b.2)
GUIX™	5.6 SP1
LevelX	5.6
TraceX®	5.2.0
GUIX Studio™	5.6.1.0
NetX Secure	5.12 SP1
NetX Duo Secure	5.12 SP1
TES D/AVE 2D	3.17

5. SSP Release Package and Installation Information

Before installing SSP standalone installer, ensure that the following items are installed on your PC:

- **Renesas e² studio ISDE v7.5.1** (download and install the e² studio Installer from the Renesas website at www.renesas.com/synergy/software)
- **GNU Arm® Compiler** (included with Renesas e² studio ISDE v7.5.1)

To install the SSP, follow these steps:

1. Download the following items for the SSP Release from www.renesas.com/synergy/software:
 - **SSP_Distribution_1.7.8.zip** (SSP Package Installer, including SSP Package)
 - **Renesas Synergy Software Package (SSP) v1.7.8 Release Note.**
2. Unzip the package and run the **SSP_Distribution_1.7.8.exe** installer.
3. Install the SSP in the root folder of a compatible e² studio installation.

Note: The default installation folder for the SSP is **C:\Renesasle2_studio**.

SSP documentation is available for download from the Synergy Software Package (SSP) page in Renesas Synergy Platform section, at www.renesas.com/synergy/ssp. Sign in to the MyRenesas account by using your existing MyRenesas or Synergy Gallery credentials, or by creating a new MyRenesas account.

6. Changes from SSP v1.7.5 to SSP v1.7.8

This section includes a list of issues fixed in SSP v1.7.8 release.

6.1 Issues Fixed in SSP v1.7.8

6.1.1 BSP for SSP Supported Platforms

Issue ID: 15739

Changed `.data.*` to `*(.data*)` and the `data_flash_symbol` in GCC linker script to `dflash` symbol. This may break compatibility for existing projects using `data_flash_symbol`.

To prevent compatibility issues, any projects using `BSP_PLACE_IN_SECTION(".data_flash")` or `BSP_PLACE_IN_SECTION_V2(".data_flash")` should update to use `BSP_PLACE_IN_SECTION(".dflash")` or `BSP_PLACE_IN_SECTION_V2(".dflash")` respectively,

Applies to: All MCUs

Issue ID: 15902

Data flash is now enabled for S1 and S3 parts in the BSP initialization.

Applies to: S3 and S1 MCU Series

Issue ID: 15903

The status of pins PA02 and PA03 is now restored after reading the board version from EEPROM in the BSP.

Applies to: S7G2 MCU Group

6.1.2 GUIX Studio

Issue ID: 15600

The GUIX Studio crashes sometimes if the **Reverse Byte Order** option is enabled when 2D Drawing Engine enabled in GUIX Studio. This issue is now fixed in GUIX studio 5.6.1.0.

Applies to: GUIX Studio

Issue ID: 15855

Synergy specific license file (`GUIX_Studio.tag`) is now included in the same directory as the GUIX Studio installer to install GUIX Studio with Synergy specific license.

Applies to: All MCUs

Issue ID: 15988

When GUIX Studio is used to export the resources to a binary file with compressed pixelmap output format, the output image is not displayed properly on the board.

This issue is fixed as part of GUIX Studio 5.6.1.0.

Applies to: GUIX Studio 5.6.1.0

6.1.3 NetX

Issue ID: 13297

Web HTTP client fails to reconnect with the server after the server has disconnected with the client. It returns error code 0x22, that is, socket is already bound. With the fix in NetX Duo 5.12 SP1, the client can successfully reconnect to the server multiple times.

Applies to: S7G2, S5D9, and S5D5 MCU Groups

Issue ID: 14484

When the `nx_web_http_server` function `nx_web_http_server_type_get()` is invoked with resource name ending with '/', the function returns a pointer to MIME string instead of the status code. With the fix in NetX Duo 5.12 SP1, the function `nx_web_http_server_type_get()` returns the status code.

Applies to: S7G2, S5D9, and S5D5 MCU Groups

Issue ID: 15218

When multiple network interfaces are used in an application, due to improper initialization in `nx_ip_thread_entry.c` file, bus fault is observed with compiler optimizations `-O0`, `-O2` and `-O3`. This issue is fixed with the NetX 5.12SP1 update.

Applies to: S7G2, S5D9, S5D5, and S5D3 MCU Groups

Issue ID: 15366

With the NetX 5.12 SP1 update, `nx_packet_release()` function has been modified to return `NX_OVERFLOW` and `NX_UNDERLOW` when a pointer overflow/underflow occurs respectively instead of `NX_PTR_ERROR`.

Applies to: S7G2, S5D9, S5D5, and S5D3 MCU Groups

Issue ID: 15769

When using PPP on NetX or PPP on the cellular framework with PAP/CHAP authentication, PPP discards the PAP authentication requests when the username or password length is zero. This issue is fixed with EL 5.12 SP1 pack. Check for NULL username and password removed.

Applies to: All MCUs

6.1.4 `nxd_mqtt_client`

Issue ID: 15961

MQTT client connection is terminated when large messages are received from the server. This issue is fixed with the NetX Duo 5.12SP1 update.

Applies to: S7 and S5 MCU Series

6.1.5 `nxd_tls_secure`

Issue ID: 15825

When making an HTTPS connection to a server implemented on a Synergy MCU from a PC running Windows® 7 professional 64-bit and the Chrome browser, Chrome was sending a two-byte alert message to the server in plain text after the connection has switched to encrypted mode if the server is using a self-signed certificate. This operation causes the server to crash with a hard fault when NetX Secure attempts to interpret the plain text alert message as an encrypted message. This issue is now fixed with NetX Duo 5.12 SP1.

Applies to: All MCUs

Issue ID: 15859

- TLS v1.1 has been deprecated from SSP and will be obsolete starting from the next SSP release. Users are advised to upgrade their projects to use TLS v1.2 instead.
- TLS v1.1 will be excluded from SSP releases made after May 2021.
- TLS v1.1 has known security vulnerabilities and users are strongly advised to upgrade to TLS v1.2.

Applies to: All MCUs

6.1.6 r_adc

Issue ID: 15559

In the Synergy configuration tool, no warning or error is being displayed to resemble the error on the maximum allowed frequency for ADC in the S1JA MCU. This is fixed by updating the constraint for ADC and by adding the maximum ADC conversion clock for all MCUs in XML.

Applies to: S1JA MCU Group

Issue ID: 15803

Calibration API was called before choosing ADC internal reference voltage, which lead to a wrong calibrated reference value .This issue was observed only for internal voltage since, by default, the ADC reference voltage was VREFH0.

This issue is now resolved by setting the ADC internal reference voltage before calling the calibration routine.

Applies to: S1JA MCU Group

Issue ID: 15861

The analog input channels for channel-10 seems to not be detected with the FMI data calculation. An error is returned for R7FS3A6783A01CNF. However, for 100 pin CFP (R7FS3A6783A01CFP), the error is not observed.

This issue has been fixed by correcting the data stored in the FMI table for ADANSA0 register of R7FS3A6783A01CNF MCU.

Applies to: R7FS3A6783A01CNF MCU

6.1.7 r_agt

Issue ID: 15876

When AGT channel 0 is configured with **Count Source** set to **AGT0 Underflow**, recursion occurs between functions `agt_source_freq_get` and `agt_clock_frequency_get` and eventually hits `NMI_Handler`. With the fix, the driver returns an error to the user indicating the invalid use case.

Applies to: All MCUs

Issue ID:15877

In AGT HAL driver, when the timer is reset, the counter is initialized with the timer period. Due to this, the timer generated pulse width is increased by one source clock width. This issue was fixed by setting the counter to a period value -1 in the reset function.

Applies to: All MCUs

6.1.8 r_flash_hp

Issue ID: 15668

Optimization of hardware functions in `flash_hp` is taken off to avoid the misalignment in sequence of execution to register write due to optimization enabled for GCC

Applies to: All MCUs

6.1.9 r_pdc

Issue ID: 15746

DMAC interrupt priority is not correctly set up in R_PDC HAL driver. Value of the DMAC interrupt priority is taken as a random value in memory, which may lead to getting the same priority as `pendsv_handler`. Then, if the system has a chance to enter `pendsv_handler` for thread scheduling, it will no longer get out and the system will stay in the loop permanently.

This issue is now fixed by configuring the DMAC interrupt priority correctly in PDC HAL driver.

Applies to: S7G2 and S5D5 MCU Group

6.1.10 r_qspi

Issue ID: 15708

1. In N25Q256A, read/write operation of a non-volatile register was leading to wrong results. This is now addressed and reading and writing the non-volatile register gives the desired data as the LSB is read/written first and MSB later.
2. In MX25L12835F, volatile and non-volatile configuration registers cannot be accessed properly due to wrong commands. This is addressed and read/write non-volatile register commands are changed as per the datasheet.

Applies to: S7G2 MCU Group

6.1.11 r_riic

Issue ID: 15884

In `r_riic` driver, when an extra clock cycle is provided to reset the I2C bus, CLO bit should be cleared automatically. If CLO bit is not cleared automatically, the I2C bus is trapped in a loop waiting for the CLO bit to be cleared. Hence, to break the loop, a timeout mechanism is implemented.

Applies to: All MCUs

6.1.12 sf_audio_playback

Issue ID: 15804

After the `sf_audio_playback_hw_dac` is initialized to play an audio tone with the `open()` API, and before playing the audio tone with `start()` and `play()` APIs, no audio tone is played as expected, but a `SF_AUDIO_PLAYBACK_HW_EVENT_PLAYBACK_COMPLETE` event is received, indicating that the playback is complete. This issue has now been fixed.

Applies to: All MCUs

6.1.13 sf_cellular

Issue ID: 14563

BG96 module was failing to fallback from NBloT network to GSM or CATM1 network SIM. It means GSM network SIM was not getting registered with GSM network if the Network Scan Sequence is set to one of the following:

NBloT->GSM->CATM1

CATM1->NBloT->GSM

NBloT->CATM1->GSM

CATM1 network SIM was not getting registered with CATM1 network if the Network Scan Sequence is set to one of the following:

NBloT->GSM->CATM1

GSM->NBloT->CATM1

NBloT->CATM1->GSM

This issue is fixed by increasing retry count to 255 for fallback from NBloT network to GSM or CATM1 cellular network SIM in BG96 module.

Applies to: Cellular Framework using BG96

Issue ID: 15543

In Cellular Framework, the `sf_cellular_deinit()` function was deleting the PPP without stopping the PPP instance, thus not terminating the PPP correctly. This issue has now been fixed.

Applies to: Cellular modules on all MCUs

6.1.14 sf_el_lx_nor

Issue ID: 15230

If QSPI devices larger than 64 MB are used, QSPI memory QSPI NOR driver reads data incorrectly for addresses > 64 MB. This issue has been fixed by using `R_QSPI_BankSelect` API to change banks to access memory size more than 64 MB.

Applies to: S7, S5, and S3 MCU Series

6.1.15 sf_el_nx

Issue ID: 15758

Functions `bsp_ethernet_phy_init ()` and `nx_ip_status_check()` for `NX_IP_LINK_ENABLED` were returning success even when no PHY hardware is present. This issue has now been fixed.

Applies to: S7G2, S5D9, and S5D5 MCU Groups

6.1.16 sf_el_tx

Issue ID: 15615

Applications trying to restart a thread after

`tx_thread_terminate/tx_thread_reset/tx_thread_resume` call have to use `tx_semaphore_put (&g_ssp_common_initialized_semaphore)` before restarting.

Applies to: All MCUs

6.1.17 sf_el_ux

Issue ID: 13487

Earlier, in the USBX CDC-ACM device class, if the user disconnected the USB cable from the PC host while the terminal is in connected state, and then plugged the USB CDC cable, if the user application checked the CDC line state parameter (DTR and RTS) immediately after the USB cable was plugged into the PC, it reflected the previous state, which is wrong. This issue is now fixed as part of the USBX 5.9 SP1 stack.

Applies to: All MCUs

Issue ID: 15370

The `ux_host_class_printer_status_get` function did not return correct status. This has now been fixed and the function returns the correct status.

Applies to: S7G2 and S5D9 MCU Groups

Issue ID: 15801

When an outgoing USB (bulk-in) transfer request is aborted, the next call to

`ux_device_stack_transfer_request()` hangs up waiting for the `INBUFM` flag to clear.

Now, `ACLRM` bit is used for clearing the FIFO buffers resulting in the `INBUFM` flag getting cleared.

Applies to: All MCUs

6.1.18 sf_memory_qspi_nor

Issue ID: 15231

If QSPI devices larger than 64 MB are used, QSPI memory QSPI NOR driver reads data incorrectly for addresses > 64 MB. This issue has been fixed by using `R_QSPI_BankSelect` API to change banks to access memory size more than 64 MB.

Applies to: S7, S5, and S3 MCU Series

6.1.19 Synergy Tools

Issue ID: 14528

When switching the device and deleting the `pincfg` file related to an old device, the project generation still holds a reference to the deleted `pincfg` file and fails to generate project content. The tool now updates the `configuration.xml` file when the pin configuration file is deleted to fix the issue.

Applies to: All MCUs

6.1.20 USBX

Issue ID: 8505

The USBX Device Users Guide has been updated with error code `UX_TRANSFER_BUFFER_OVERFLOW` to indicate buffer overflow error.

Applies to: All MCUs

Issue ID: 14091

Earlier, `ux_device_class_hid_report_set` API always returned error, even though the HID device successfully received an event from the host. This issue is now fixed as part of the USBX 5.9 SP1 stack.

Applies to: All MCUs

Issue ID: 15381

The `ux_host_class_hid_idle_set` API information is now documented in the USBX Host Stack User Guide.

Applies to: All MCUs

Issue ID: 15814

With the update to the **Get/Set** feature in Express Logic code, the **GetReport** transfer failing issue is fixed. Additionally, support to configure callback function from XML is added.

Applies to: All MCUs

Issue ID: 15834

In USBX device class HID application, `device event notification callback` function is required for various device event notifications.

If this callback function is not configured in the configurator, the framework disconnects the device upon receiving the suspend signal from the host.

Therefore, to pass this **Suspend/Resume** compliance test, the user needs to configure the `device event notification callback` in the configurator.

Applies to: All MCUs

Issue ID: 15872

Debounce logic is implemented according to USB specifications in the USB host. This is to ensure stabilization of the USB devices during sudden electrical/mechanical movements.

Applies to: S7, S5, and S3 MCU Series

7. Known Issues, Limitations, and Additional Usage Notes for SSP v1.7.8

7.1 BSP for SSP Supported Platforms

Issue ID: 10664

If a user is using the trace buffer for debugging and has data stored in the RAM at addresses above 0x2000 4000, that data will be overwritten by the trace buffer when debugging.

Applies to: S128 and S1JA MCU Groups

Workaround: The S128 linker script currently allocates 1K for the trace buffer at 0x2000 0000. This allocation could be removed, freeing up the 1K mistakenly reserved for the trace buffer. Using the e² studio trace buffer function will store 1K of the trace buffer data beginning at 0x2000 4000, so that 1K of RAM must not be used by the application if the trace buffer is to be used for debugging.

Issue ID: 15837

Single linker script is available for all S5D5 devices, while these devices have different memory footprints.

Applies to: S5 MCU Series

Workaround: Update the memory regions in the linker script manually.

7.2 Crypto/r_sce

Issue ID: 11147

Only data input lengths that are multiples of AES block size are supported for AES encryption/decryption APIs for XTS chaining mode.

Applies to: S7, S5, and S3 MCU Series

Workaround: None

7.3 GUIX

Important Information regarding API deprecation, updates, and compatibility with GUIX 5.6

Some of the APIs in GUIX 5.6 stack have been updated or deprecated and replaced with enhanced versions; additionally, there are changes in the stack that could potentially impact compatibility of existing applications that use GUIX when upgrading to SSP v1.7.8. For more information on these changes and compatibility mode settings for GUIX, refer to the Module Usage Notes for GUIX Port module under the Module Overviews section in the SSP v1.7.8 User's Manual.

Issue ID: 16051

An application using fonts with 1 bpp and 4 bpp format along with hardware rendering will give a compilation error.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: None

7.4 ISDE User Experience

Issue ID: 7665

When using the Synergy Software Configurator in e² studio/SSC, if you rename a thread on the Threads tab and generate code, a new thread_entry.c file is created with template content, and the old thread_entry.c file remains in the project. If you have edited the thread_entry.c file, your changes are not moved to the new file. The old file remains in the project. It will not be called; it causes a build error if not removed from the project manually.

Applies to: All MCUs

Workaround: Manually move any edits (if made) from the old thread_entry.c file to the new thread_entry.c file, then manually delete the old thread_entry.c file from your project.

Issue ID: 12826

If the Synergy Configuration window is maximized in e² studio, the property window will not be updated.

Applies to: All MCUs

Workaround: Do not maximize the Synergy Configuration window before clicking on elements when editing the properties.

Issue ID: 12908

Applies to: All MCUs

A multiple symbol definition error may occur during linkage if an X-Ware library component and the corresponding source component such as ux and ux_src are included. If this occurs, remove the library such as libux.a from the list of libraries used by the linker.

For GCC, this in the **Cross ARM C Linker > Libraries section of the C/C++ Build > Settings** in the project **Properties**.

For IAR, this in the **IAR Linker for ARM > Library section of the C/C++ Build > Settings** in the project **Properties**.

Module Names: ux (USBX), tx (ThreadX), nx (NetX), nxd (NetX Duo), fx (FileX), gx (GUIX), ux_host_class_XXX (USBX Host Classes), ux_device_class_XXX (USBX Device Classes).

Issue ID: 13854

When debugging a project with a large number of threads (for example, 150 threads) with the RTOS Resource view open, e² studio might hang and become unresponsive.

Applies to: All MCUs

Workaround: Make the RTOS Resource View small and expand it once the Debug Tree View has finished updating.

7.5 NetX

Issue ID: 12951

Users will not be able to use TLS 1.0 for secure connection.

Applies to: S7G2, S5D9, S5D5, and S5D3 MCU Groups

Workaround: None

Issue ID: 14293

Build warnings will be observed on compiling NetX Duo BSD application with GCC7 compiler.

Applies to: CM4 MCUs (S7, S5, and S3 MCU Series)

Workaround: None

7.6 nxd_tls_secure

Issue ID: 14714

For ECC Cipher Suite with AES GCM Cipher algorithm, the output buffer size is defined as 2048 bytes. If the incoming message is greater than 2048 bytes, data transfer will fail.

Applies to: S7 and S5 MCU Series

Workaround 1:

The application should breakdown a large data buffer into 2K chunks.

Workaround 2:

- Define `NX_CRYPTO_AES_OUTPUT_BUF_SIZE` to 4096 in `sf_el_nx_crypto\nx_crypto_aes_sce.h`
- Increase the metadata buffer size for the application accordingly.

Issue ID: 15051

Warnings will be observed on compiling nxd applications with GCC7.

Applies to: S7 and S5 MCU Series

Workaround: None

7.7 Pin Mapping Issues

Issue ID: 10864

The pin configuration tab in the configurator cannot be used to configure the opamp or analog comparators for every use case.

Applies to: S7G2, S5D9, S5D5, S5D3, S3A7, S3A3, S128, S124 MCU Groups

Workaround: Configure the pins manually in user defined code.

Issue ID: 12261

The DAC8 output pin is not being configured when it is configured through ISDE.

Applies to: S3A3, S128, and S1JA MCU Groups

Workaround: Configure the DAC8 output pin manually.

Issue ID: 14452

The current driver uses AVCC0 as the reference voltage for internal ADC. When internal voltage measurement or VREFH0, VREFL0 is selected, pin conflict is observed in the tools and the driver does not support these features.

Applies to: S3 and S1 MCU Series

Workaround: None

7.8 r_agt_input_capture

Issue ID: 15070

While capturing the pulse width with AGT input capture, after measurement completion, the counter and overflow value returned from callback are correct, but the same values read simultaneously with `lastCaptureGet` API are incorrect.

Applies to: All MCUs

Workaround: None

7.9 r_cgc

Issue ID: 15945

The SCKDIVCR register bits 18 to 16 are not initialized as expected in cgc initialization because of which the processor is put in a state where it has issues with JLINK connectivity. Note that this issue is observed only with certain clock frequencies.

Applies to: S3A6 MCU Group

Workaround: Use a different clock frequency.

7.10 r_ctsu

Issue ID: 6927

R_CTSU_Update_Parameters() returns error. Not all return codes are described in the function header.

Some return codes are as follows:

SSP_ERR_NOT_OPEN when mode is set to CTSU_MODE_UNCONFIGURED

SSP_ERR_IN_USE when Measurement Status Counter set to non-zero value or CTSU Data Transfer Status flag is set.

SSP_ERR_CTSU_RC_OVERFLOW when CTSUROVF flag is set

SSP_ERR_CTSU_SC_OVERFLOW when CTSUSOVF flag is set

SSP_ERR_CTSU_ICOMP when TSCAP Voltage Error Monitor flag is set

Applies to: All MCUs

Workaround: In cases where the returned error code is not described in the function header, refer to the description of the return code in `ssp_common_api.h`.

Issue ID: 6928

If the customer calls R_CTSU_Read while the driver is in an uninitialized state, then the documented return code is SSP_SUCCESS, but the actual return code is SSP_ERR_NOT_OPEN. When calling R_CTSU_Read while the driver is uninitialized, the application should expect a return code of SSP_ERR_NOT_OPEN.

The R_CTSU_Read() function is not sufficiently tested with the CTSU_READ_FILTERED_REF_ICO_VALUES_SEL and CTSU_READ_FILTERED_REF_ICO_VALUES_ALL options

Applies to: All MCUs

Workaround: None

Issue ID: 6929

Auto-calibration, auto-scan and auto-drift compensation features are not available in the r_ctsu driver.

Applies to: All MCUs

Workaround: None

Issue ID: 6931

Parameter checking for NULL parameters is not implemented. Passing in a NULL parameter to the r_ctsu API will result in undefined system operation.

Applies to: S7G2, S5D9, S5D5, S3A7, S128, and S124 MCU Groups

Workaround: When using this driver, make sure that the control structure passed to r_ctsu API is not NULL.

Issue ID: 8731

In case of a hardware issue where the channel capacitance has an invalid value (due to board layout), the CTSU data acquisition fails. The code waits in a loop for the data, and does not return.

Applies to: All MCUs

Workaround: Ensure that the PCB design provides adequate parasitic capacitance per the design layout guidance.

7.11 r_riic

Issue ID: 16047

When the user opens the `r_riic` module in fast mode and tries to communicate with IIC `read()` or `write()`, there is some SCL clock deviation from its expected value (that is, 400KHz). This is because when the BRCL and BRCH register values are calculated to generate the expected clock (in the `riic_clock_settings()` in the `r_riic open()`), the SCLn line rise time (`tr`), fall time (`tf`) and Number of digital noise filters (`nf`) are not included in the calculation.

Applies to: All MCUs

Workaround: None

Issue ID: 16048

In the function `riic_abort_hw_master()` in the file `r_riic.c`, the RIIC register values are not restored after IIC internal reset. Due to this, whenever a NACK is received on the IIC bus, and the application hits the function `riic_abort_hw_master()` as a part of NACK error handling, it is observed that bit rate after error handling varies when compared to prior to error handling.

Applies to: All MCUs

Workaround: None

7.12 r_sci_spi

Issue ID: 10962

Each MCU supports a different range of bit rates depending on the speed of the clock provided to the SCI-SPI peripheral. To get the maximum supported bit rate for a particular MCU, see the corresponding MCU User's Manual.

Applies to: All MCUs

Workaround: None

Issue ID: 15574

In an application, if using DTC for data transfer, SCI SPI can experience an overrun error if the same application makes heavy use of DMAC and/or another DTC instance. This is because the DMAC has a high priority over DTC in arbitration for the mastership of the DMA bus. Also, arbitration between different triggers/transfers in DTC is done based on the interrupt/trigger priority. So, if the DMAC or DTC triggered by high priority interrupt/task is accessing the DMA bus and SCI SPI is receiving the data at the same time, DTC used by SCI SPI will not be able to access the bus to transfer the received data into the memory, causing SCI SPI to return an overrun error.

Applies to: All MCUs

Workaround: Overrun error can be averted with one of the following options:

1. If SCI SPI uses DTC for data transfer, avoid the use of DMAC or another DTC instance in an application.
2. If DMAC/DTC is a must for other data transfers, avoid the use of DTC with SCI SPI.
3. Use RSPI instead of SCI SPI. The RSPI hardware can handle overrun conditions.

7.13 r_sci_uart

Issue ID: 16028

When `baudSet()` API is used to set the baud rate, the user receives one byte less, and the first two bytes of the actual send data are swapped.

Applies to: S3 and S1 MCU Series

Workaround:

1. Re-enable the TE bit in the `baudSet()` function.
2. Set baud rate in stack properties.

7.14 r_sdmmc

Issue ID: 15942

When doing a write operation with FileX with `r_sdmmc` as the underlying layer, and with `r_sdmmc` property WP(write protect) set to "Not Used", and the corresponding WP pin in pin configuration set to "NONE"(as it is unused), the write operation fails.

Applies to:S5D9 and S5D3 MCU Groups

Workaround: The write passes when the WP pin in pin configuration is set to its hardware pin instead of to "NONE."

7.15 sf_ble

Issue ID: 9225

HID profile client mode is not supported by RL78G1D. As a result, the BLE framework implementation of the HID profile will also not support the HID profile client mode. Applications using a BLE framework for RL78G1D will not be able to use the HID profile in client mode.

Applies to: All MCUs

Workaround: None

Issue ID: 9256

The projects using RL78G1D framework will see compilation warnings. All the warnings are in the 3rd party RL78G1D driver code and will not have impact on the user applications. The RL78G1D framework files do not have any warnings.

Applies to: RL78G1D on all Synergy MCUs

Workaround: None

7.16 sf_cellular

Issue ID: 14566

Automatic time zone update disable functionality does not work. Even when the user disables automatic time zone update, the current updated time is received.

Applies to: CAT3, CAT1, and Quectel BG96 modules

Workaround: None

7.17 sf_el_gx

Issue ID: 15783

Build warnings are being observed when compiling GUIX Source with GCC 7.2.1.

Applies to: S7G2 and S5D9 MCU Group

Workaround: None

7.18 sf_el_tx

Issue ID: 13678

SF_CONTEXT_SAVE and SF_CONTEXT_RESTORE (in `bsp_common.h`) should only be defined if TX_ENABLE_EXECUTION_CHANGE_NOTIFY or TX_ENABLE_EVENT_TRACE is defined.

Applies to: All MCUs

Workaround: None

7.19 sf_el_ux

Issue ID: 8574

The current `sf_el_ux` HCD driver does not enable the double buffer feature for bulk out PIPEs, which is supported by USB hardware. Because of that, USB data throughput for data write through a bulk out PIPE will be less than the value for double buffer-enabled. This issue is only for data write (bulk OUT). Double buffering is supported for data read (bulk IN).

Applies to: S7, S5, and S3 MCU Series

Workaround: None

Issue ID: 11332

SF_EL_UX DCD driver is not functional when configuring DTC as a transfer component to the USBX Class stack in the Synergy Configuration tool.

In the USBX DCD Port driver (`sf_el_ux` Device Controller Driver), when DTC is selected as the transfer component in the stack configuration series, the compilation errors that were displayed earlier for the S1 MCU Series are no longer displayed (for S124, S128, S1JA MCU Groups).

On non-S1 MCUs (that is S7, S5, and S3 MCU Series), there are no compilation errors (build is success) but the DCD driver is not functional.

Applies to: All MCUs

Workaround: None

Issue ID: 13481

The USB host sends out a PING packet after receiving NAK or NYET handshake from the device. However, it also sends out a PING packet for ACK handshake, which is not expected behavior according to the USB 2.0 specification.

Applies to: All Synergy MCUs supporting USBX Host

Workaround: None

Issue ID: 13528

In the USBX Device Class CDC, in blocking mode, write/read calls made to the `sf_el_ux` DCD driver do not support the timeout feature, which may result in indefinite waiting for the host transfer to get completed.

Option 1: In order to use the non-blocking or callback mode in USBX CDC device class, call the `ux_device_class_cdc_acm_ioctl()` API in the application to use transmission with callback. See the latest *USBX Device Stack User Guide* for more information on the Device Class APIs.

Option 2: Call the `ux_device_stack_transfer_abort()` API from the other threads in the application to abort the pending transfer requests.

Applies to: All MCUs

Workaround: None

Issue ID: 15368

`ux_host_class_printer_name_get` function does not support all IEEE 1284 Device ID strings.

Applies to: S7G2 and S5D9 MCU Group

Workaround: None

Issue ID: 15873

In USBX Device CDC class, write API `_ux_device_class_cdc_acm_write()` is used to send data to CDC host. But, write API returns completion status earlier than the actual write operation completes.

Applies to: All MCUs

Workaround: None

7.20 `sf_i2c`

Issue ID: 14618

With GCC 7.2 and optimization level `-Og`, `sf_i2c_read` API (with `sci_i2c` driver) intermittently hangs when invoked with a timeout value of 0 instead of returning timeout error.

Applies to: All MCUs

Workaround:

- Use optimization level `-O2`.
- Instead of `sci_i2c`, use `r_riic` as the lower-level driver.

7.21 `sf_touch_ctsu`

Issue ID: 6858

1. When a channel is set to NULL, `SF_TOUCH_CTSU_Read()` returns `SSP_ERR_INTERNAL`.
2. Return values from ThreadX API calls are not checked in the framework. This can lead to functional issues in the framework when ThreadX APIs return error. Framework may not work as expected in such error cases since errors are not handled.
3. With valid callback and context if `callback_index` is set to `SF_TOUCH_CTSU_CFG_MAX_WIDGET_TYPES (= 3)`, `SF_TOUCH_CTSU_Open()` returns `SSP_ERR_OUT_OF_MEMORY`.

Applies to: All MCUs

Workaround: None

Issue ID: 6859

`SF_TOUCH_CTSU_Read()` returns error value `SSP_ERR_INTERNAL` if semaphore get or put are not successful.

Applies to: All MCUs

Workaround: None

7.22 `sf_touch_ctsu_button`

Issue ID: 6882

1. valid range for `button_count` is 0 to less than `SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12)`
2. For `button_count` values outside the range, `SF_TOUCH_CTSU_Button_Open()` returns error `SSP_ERR_ASSERTION`.

Applies to: All MCUs

Workaround: None

Issue ID: 6883

For `button_count` values outside the range, `SF_TOUCH_CTSU_Button_Open()` returns error `SSP_ERR_ASSERTION` and hence buttons outside the range cannot be operated.

Applies to: All MCUs

Workaround: `Button_count` values must be set to value 0 to less than `SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12)`.

7.23 sf_Wifi**Issue ID:** 8394

The projects using GT202 framework will see compilation warnings. All the warnings are in the 3rd party GT202 driver code. The GT202 framework files do not have any warnings. The warnings should not impact the user applications.

Applies to: WiFi Framework for GT202 on S7G2, S3A7, S5D9, S5D5, S3A6 (only socket), S3A3 MCU Groups

Workaround: None

Issue ID: 12742

GT202 module supported by WiFi Framework is affected by WPA2 KRACK issue.

Applies to: GT202 module supported by WiFi Framework

Workaround: None

Issue ID: 14126

WiFi WPS functionality does not work with WPA security.

Applies to: WiFi Framework using GT202

Workaround: None

Issue ID: 14314

If an ongoing WPS session gets terminated by a peer WiFi device, then the GT202 driver hangs. The GT202 driver API for WPS is called by invoking WiFi Framework APIs which use mutex. When GT202 driver hangs, it will cause the WiFi WPS API to hang, resulting in WiFi APIs returning mutex error.

Applies to: All MCUs supported by GT202

Workaround: None

Issue ID: 15793

1. In `netx_next_received_packet()` function, **else** part of the condition `((length - *p_total_len) < data_len)` is not reachable.

This piece of code performs packet fragmentation and the GT202 does not perform packet fragmentation and hence the piece of code is not executed.

2. In function `gt202_wps_start()`, **else** part of condition `if (SSP_SUCCESS == ssp_err)` is not reachable. That is, table for mapping GT202 error to SSP error (`sf_wifi_gt202_ssperr_map`) always returns `SSP_SUCCESS` (as Net parameter `net_params` is initialized with 0 and holds same value throughout) irrespective of inputs, this causes unreachable branch.

The value of `net_params` may be altered by the call:

```
ioctl_struct.data = ((QOSAL_VOID *) &net_params);

ioctl_struct.length = sizeof(net_params);

retval = ath_ioctl_handler (&driver_handle->enet, &ioctl_struct);
```

In which case the `if(SSP_SUCCESS == ssp_err)` may not always be equal to `SSP_SUCCESS`.

Applies to: All MCUs

Workaround: None

7.24 SSP IAR Support

Issue ID: 12845

Cannot debug the program when selecting the option **Download and Debug** in EWSYN or **Debug** in e² studio for the first time after setting an ID code in the project.

Applies to: All MCUs

Workaround: When the debug fails, select the option to **Debug without download** in EWSYN or **Debug** in e² studio again to successfully debug the program.

Issue ID: 13900

In some cases, the build fails with the error “Secure builder required” after migrating to a newer SSP version in EWSYN.

Applies to: All MCUs

Workaround: Select **Project > Make (F7)** after the issue occurs. The project should then build without errors.

Issue ID: 14485

Library projects which use many/long `include` paths cause the compiler command line to exceed system limit and fails to build the library.

Applies to: Projects created with IAR compiler in e² studio.

Workaround: None

7.25 SSP XMLs for ISDEs

Issue ID: 12857

Creating a project with a custom board pack might not reflect the customized values set for the properties in that custom board pack.

Applies to: All MCUs

Workaround: None

7.26 Synergy Tools

Issue ID: 11556

Synergy builder is excluded from the tool command pattern when changing the toolchain from IAR 7.x to IAR 8.x, which leads to a build error that the secure builder is required when trying to build the project after migrating.

Applies to: All MCUs

Workaround:

The following workaround can be used to migrate projects with IAR 7.x to IAR 8.x:

1. Add environment variable `SECURE_BUILD_COMMAND`: `${renesas.support.targetLoc:synergy-build} /isdebuild`
2. Update command line pattern IAR C/C++ Compiler for ARM setting if the following command is missing:
`${SECURE_BUILD_COMMAND}`
3. Update command line pattern IAR C/C++ Assembler for ARM if the following command is missing:
`${SECURE_BUILD_COMMAND}`

Issue ID: 12584

An error occurs when setting the watchpoint at certain addresses. Debug sessions cannot be started when these watchpoints with errors are still present.

Applies to: S5D9 MCU Group

Workaround: Remove the watchpoints from the breakpoints view and start the debug session.

Issue ID: 12925

When exporting the project, selecting the option for `.tar` format does not export the project in `.tar` format, but exports it in `.zip` format.

Applies to: Tools

Workaround: Edit the archive file name field by replacing the `.zip` with `.tar`, and the project will be exported in `.tar` format.

Issue ID: 14436

Some of the old projects with customized stacks might fail after migrating to e² studio v7.3 because the default modules get repopulated in the stack.

Applies to: All MCUs

Workaround: The user explicitly needs to delete the modules that are repopulated after migration.

Issue ID: 14747

When SSP v1.6.0 and a version later than SSP v1.6.0 are both installed, Developer assistance node in the project created with SSP v1.6.0 shows the function `wpstart`, which is not supported in SSP v1.6.0. Dragging and dropping the API to the source file will show a message about an unresolved method.

Applies to: Projects created with SSP v1.6.0 and using the RDS file created with later versions of SSP

Workaround: Do not drag and drop the `wpstart` function from the Developer Assistant node in SSP v1.6.0.

Issue ID: 15093

Using the option "Rename and import existing C/C++ project" causes intermittent failure in importing the project, and gives an error message.

Applies to: All MCUs

Workaround: None

Issue ID: 15104

e² studio v7.3.0 is sensitive with respect to the casing of linker script file names. This is experienced only in the projects created with the previous version of e² studio where the linker script names do not exactly match in casing. In this case, the customer would experience a build error saying that the linker script is not found.

Applies to: All MCUs

Workaround: If the build is failing with **.ld not found** error, go to the linker configuration in e² studio project properties and delete the linker script entry.

Issue ID: 15203

When performing a clean build of a project in command line, the debug build configuration fails to be cleaned as the length of the `rm` command line has not adhered to the limit of the console interface.

Applies to: All MCUs

Workaround: None

Issue ID: 15330

Projects created with SSP versions prior to SSP v1.6.3 and edited to remove the default lower module fail to build when migrated to SSP v1.6.3.

Applies to: Projects created in earlier versions that have been edited by removing the default lower level module in thread stacks

Workaround: Open the threads tab before building the project

Issue ID: 15339

Default property value of the IP address does not get picked up for existing projects after changes to the pack. Opening existing projects shows the previously saved value instead of the default value from the pack.

Applies to: Projects which use the packs with the change for IP address

Workaround: None

Issue ID: 15536

In e² studio 7.4, only threads that have a run count greater than 0 will be shown in the **Debug** view. When one of the threads has a run count of 0, all the threads after that check do not populate in the **Debug** view.

Applies to: All MCUs

Workaround: None

Issue ID: 15606

When starting to debug a project, sometimes the program stops executing after clicking resume at the reset_handler.

Applies to: All MCUs

Workaround: Click reset or restart button to continue running the program

Issue ID: 15653

The Synergy project fails to compile when including the macros `_has_include` or `_has_include_next`.

Applies to: All MCUs

Workaround: Go to the properties of the source file where the macro has been added and remove the `$(SECURE_BUILD_COMMAND)` from the command line pattern. The project should now compile properly.

Issue ID: 15685

Stack Analysis view cannot install when selecting a Synergy device in the installer.

Applies to: All MCUs

Workaround: One of the following workarounds can be used to fix the issue:

1. Add the Stack Analysis plugin by re-launching installer with "Modify" option
2. Add the plugin through **Help > Install New Software**.

7.27 Tes

Issue ID: 14095

The rendering of concave polygons is not supported when D/AVE 2D drawing engine is enabled.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: Disable D/AVE 2D drawing engine to render concave polygons.

Issue ID: 15762

An application using pixelmaps to fill the shapes does not render pixelmaps properly inside the shapes if the pixelmaps width and height are not the power of 2.

Applies to: S7G2 and S5D9 MCU Groups

Workaround: The pixelmaps are properly drawn inside the shapes if pixelmap width and height are the power of 2.

7.28 Tools Development

Issue ID: 15202

TraceX fails to launch and gives a license error when an existing TraceX installation is overwritten by reinstalling TraceX using TraceX standalone installer.

Applies to: All MCUs

Workaround: Uninstall the existing TraceX application and install it again.

7.29 USBX

Issue ID: 8647

The USB throughput for file `read/write` operation with USBX Device Class Mass Storage is not consistent and may vary for every measurement.

Applies to: All MCUs

Workaround: None

Issue ID: 14100

Warnings for “this statement may fall through” will be observed when compiling USBX Device class source code.

Applies to: All MCUs

Workaround: None

Issue ID: 15857

An infinite loop occurs when a large file is copied on an SD card by using USBFS (DMA enable) with the IAR compiler.

Applies to: All MCUs

Workaround: USBFS (CPU) with the IAR compiler or USBFS (DMA enable) with the GCC compiler can be used.

Issue ID: 15990

The Mode Sense function `_ux_device_class_storage_mode_sense` sets the WP information in the wrong mode parameter header format. USBX device mass storage class application will not be able to notify the host regarding the write protection information of the storage media.

Applies to: All MCUs

Workaround: None

Issue ID: 16007

USB CDC ACM fails to receive data only when 64 bytes are sent. But when multiples of 64 bytes are transferred, USB CDC ACM receives data properly.

Applies to: All MCUs

Workaround: None

8. Complete List of Modules Supported in this Release

These modules are available on the respective MCUs based on the following criteria:

- If the core functionality of the module has been tested and works on an MCU, even if it has known bugs, then the module is supported on the MCU.
- If the core functionality is broken or not tested on an MCU, then that module is not supported on the MCU.
- If a module is independent of the underlying MCU hardware or HAL drivers, and has been tested on a particular Synergy MCU, the following table indicates that this module is supported on all the Synergy MCUs that the underlying driver/framework/stack depend on have been tested.

8.1 BSP and Driver Modules Available in this Release

Module Name	SSP Feature	Supported Synergy MCU Groups
BSP	Board Support Package	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_acmphs	Analog Comparator High Speed	S1JA, S3A7, S5D9, S5D5, S5D3, S7G2
r_acmplp	Analog Comparator Low Power	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7
r_adc	A/D Converter	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_agt	Asynchronous General Purpose Timer	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_agt_input_capture	AGT Input Capture	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_analog_connect	Analog Connect	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_cac	Clock Frequency Accuracy Measurement Circuit	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_can	Controller Area Network	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_cgc	Clock Generation Circuit	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_crc	Cyclic Redundancy Check Calculator	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_ctsu	Capacitive Touch Sensing Unit	S124, S128, S3A7, S5D5, S5D9, S7G2
r_dac	Digital to Analog Converter	S124, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_dac8	8-bit Digital to Analog Converter	S128, S1JA, S3A1, S3A3, S3A6
r_dmac	Direct Memory Access Controller	S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_doc	Data Operation Circuit	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_dtc	Data Transfer Controller	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_elc	Event Link Controller	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_flash_hp	Flash Memory, High Performance	S5D3, S5D5, S5D9, S7G2
r_flash_lp	Flash Memory, Low Power	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7
r_fmi	Factory Microcontroller Information	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_glcd	Graphics LCD Controller	S5D9, S7G2
r_gpt	General Purpose Timer	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2

Module Name	SSP Feature	Supported Synergy MCU Groups
r_gpt_input_capture	General Input Capture	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_icu	Interrupt Controller Unit	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_ioport	General Purpose I/O Ports	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_iwdt	Independent Watchdog Timer	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_jpeg_common	JPEG Common	S5D9, S7G2
r_jpeg_decode	JPEG Decode	S5D9, S7G2
r_jpeg_encode	JPEG Encode	S5D9, S7G2
r_kint	Keyboard Interrupt Interface	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_lpm†	Low Power Mode	S124, S3A7, S7G2
r_lpmv2_s1ja	Low Power Mode V2 for S1JA	S1JA
r_lpmv2_s124	Low Power Mode V2 for S124	S124
r_lpmv2_s128	Low Power Mode V2 for S128	S128
r_lpmv2_s3a1	Low Power Mode V2 for S3A1	S3A1
r_lpmv2_s3a3	Low Power Mode V2 for S3A3	S3A3
r_lpmv2_s3a6	Low Power Mode V2 for S3A6	S3A6
r_lpmv2_s3a7	Low Power Mode V2 for S3A7	S3A7
r_lpmv2_s5d3	Low Power Mode V2 for S5D3	S5D3
r_lpmv2_s5d5	Low Power Mode V2 for S5D5	S5D5
r_lpmv2_s5d9	Low Power Mode V2 for S5D9	S5D9
r_lpmv2_s7g2	Low Power Mode V2 for S7G2	S7G2
r_lvd	Low Voltage Detection Driver	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_opamp	Operational Amplifier	S128, S1JA, S3A1, S3A3, S3A6, S3A7
r_pdc	Parallel Data Capture Unit	S5D5, S7G2
r_qsapi	Quad Serial Peripheral Interface	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
r_riic	IIC	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_riic_slave	IIC Slave	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_rsapi	Serial Peripheral Interface	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_rtc	Real-time Clock	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_sci_i2c	Serial Communication Interface I2C	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_sci_spi	Serial Communication Interface SPI	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_sci_uart	Serial Communication Interface UART	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_sdadc	Sigma Delta ADC	S1JA
r_sdmcc	SDHI Driver for SDIO and SD/MMC Memory Devices	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
r_slcdc	Segment LCD Controller	S3A1, S3A3, S3A6, S3A7
r_ssi	(Inter-IC Sound) Interface [old: Serial Sound Interface] or r_i2s	S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2

Module Name	SSP Feature	Supported Synergy MCU Groups
r_wdt	Watchdog Timer	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
r_sce [#]	Cryptographic Library (HAL interfaces)	See table note on Cryptographic Functions

[#] **Cryptographic Functions:** Section 8.4 lists cryptographic functions available for each MCU in this release; these functions are accessible as part of r_sce/cryptographic library.

8.2 Framework Modules Supported in this Release

Module Name	SSP Feature	Supported Synergy MCU Groups
sf_adc_periodic	Periodic Sampling ADC	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_audio_playback	Audio Playback	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_audio_playback_hw_dac	Audio Playback HW DAC	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_audio_playback_hw_i2s	Audio Playback HW I2S	S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_audio_record_adc	Audio Record ADC	S124, S128, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_audio_record_i2s	Audio Record I2S	S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_ble_rl78g1d	BLE Framework	S124, S128, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_ble_rl78g1d_onboard_profile	BLE Framework Onboard Profiles	S124, S128, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_block_media_lx_nor	Block Media Interface for LevelX NOR	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_block_media_qspi	Block Media Interface for QSPI	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_block_media_ram	Block Media Interface for RAM	S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_block_media_sdmmc	Block Media Interface for SD Multi Media Card	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_comms_telnet	Telnet Communications	S5D3, S5D5, S5D9, S7G2
sf_console	Console	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_fx	Synergy FileX interface	S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_gx	Synergy GUIX Interface	S5D9, S7G2
sf_el_lx_nor	Synergy LevelX NOR Interface	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_nx	Synergy NetX Interface	S5D5, S5D9, S7G2
sf_el_nx_comms	Synergy NetX Communication Interface	S5D5, S5D9, S7G2
sf_el_ux	Synergy USBX Interface	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_ux_comms†	Synergy USBX Communication Interface	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_ux_comms_v2	Synergy USBX Communication Interface V2	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2

Module Name	SSP Feature	Supported Synergy MCU Groups
sf_external_irq	External Interrupt	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_i2c	I2C Framework	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_jpeg_decode	JPEG Decode	S5D9, S7G2
sf_memory_qspi_nor	Memory QSPI NOR	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_message	Inter-Thread Messaging	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_power_profiles†	Power Mode Profile	S124, S3A7, S7G2
sf_power_profiles_v2	Power Mode Profile V2	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_spi	SPI Framework	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_tes_2d_drw	2D Drawing Engine Framework	S5D9, S7G2
sf_thread_monitor	Thread Monitor (Watchdog)	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_touch_ctsu	Capacitive Touch Sensing Unit	S124, S128, S3A7, S5D9, S7G2
sf_touch_ctsu_button	Capacitive Touch Sensing Unit Button	S124, S128, S3A7, S5D9, S7G2
sf_touch_ctsu_slider	Capacitive Touch Sensing Unit Slider	S124, S128, S3A7, S5D9, S7G2
sf_touch_panel_i2c	Touch Panel I ² C	S5D9, S7G2
sf_touch_panel_v2	Touch Panel Version 2	S5D9, S7G2
sf_uart_comms	UART Framework	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_wifi_gt202	WiFi Framework	S124, S128, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_wifi_gt202_onchip	WiFi framework on Chip Stack	S124, S128, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_cellular_catm1	Cellular Framework Quectel BG96 CATM1	S5D9, S7G2
sf_cellular_catm1_socket	Cellular Framework Quectel BG96 CATM1 Socket	S5D9, S7G2
sf_cellular_cat1	Cellular Framework Nimbelinek CAT1	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_cellular_cat1_socket	Cellular Framework Nimbelinek CAT1 Socket	S128, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_cellular_cat3	Cellular Framework Nimbelinek CAT3	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
sf_cellular_cat3_socket	Cellular Framework Nimbelinek CAT3 Socket	S128, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_crypto#, ##	Cryptographic Framework	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
sf_el_nx_crypto	Cryptographic Framework-Shim layer	S5D3, S5D5, S5D9, S7G2

Cryptographic Functions: Section 8.4 lists cryptographic functions available for each MCU in this release; these functions are accessible as part of r_sce/cryptographic library.

Framework Interfaces for Cryptographic Functions (sf_crypto) available for this release include: HASH, TRNG, and Key Generation (RSA and AES), Key Installation, Signature, and Cipher.

† Indicates a module that is deprecated starting with SSP v1.3.0 and all subsequent versions. Deprecated modules will only be available to maintain compatibility with existing projects that may be using them. It is highly recommended that new projects use the recommended replacements and not use deprecated modules. For details, see the *SSP User's Manual*.

8.3 Third-Party Modules Supported in this Release

Module Name	SSP Feature	Supported Synergy MCU Groups
fx	FileX	S124, S3A3, S3A6, S3A7, S5D9, S7G2
gx	GUIX	S5D9, S7G2
nx	NetX	S5D9, S7G2
nx_auto_ip	NetX Auto IP	S5D9*, S7G2
nx_bsd	NetX BSD	S5D9*, S7G2
nx_dhcp_client	NetX DHCP Client	S5D9*, S7G2
nx_dhcp_server	NetX DHCP Server	S5D9*,
nx_dns_client	NetX DNS Client	S5D9*, S7G2
nx_ftp_client	NetX FTP Client	S5D9*, S7G2
nx_ftp_server	NetX FTP Server	S5D9*, S7G2
nx_http_client	NetX HTTP Client	S5D9*, S7G2
nx_http_server	NetX HTTP Server	S5D9*, S7G2
nx_pop3	NetX POP3	S5D9*, S7G2
nx_ppp	NetX PPP	S5D9*, S7G2*
nx_smtp_client	NetX SMTP Client	S5D9*, S7G2
nx_snmp	NetX SNMP	S5D3*, S5D5*, S5D9*, S7G2
nx_snmp_client	NetX SNMP Client	S5D9*, S7G2
nx_telnet_client	NetX Telnet Client	S5D9*, S7G2
nx_telnet_server	NetX Telnet Server	S5D9*, S7G2
nx_tftp_client	NetX TFTP Client	S5D9*, S7G2
nx_tftp_server	NetX TFTP Server	S5D9*, S7G2
nxd	NetX Duo Stack	S5D9, S7G2
nxd_auto_ip	NetX Duo Auto IP	S5D9*, S7G2
nxd_bsd	NetX Duo BSD	S5D9*, S7G2
nxd_dhcp	NetX Duo DHCP IPv4 Client	S5D9*, S7G2
nxd_dhcp	NetX Duo DHCP IPv6 Client	S5D9*, S7G2
nxd_dhcp_server	NetX Duo DHCP IPv4 Server	S5D9*, S7G2
nxd_dhcp_server	NetX Duo DHCP IPv6 Server	S5D9*, S7G2
nxd_dns	NetX Duo DNS Client	S5D9*, S7G2
nxd_ftp_client	NetX Duo FTP Client	S5D9*, S7G2
nxd_ftp_server	NetX Duo FTP Server	S5D9*, S7G2
nxd_http_client	NetX Duo HTTP Client	S5D9*, S7G2
nxd_http_server	NetX Duo HTTP Server	S5D9*, S7G2
nxd_nat	NetX Duo NAT	S5D9*, S7G2
nxd_pop3	NetX Duo POP3	S5D9*, S7G2
nxd_ppp	NetX Duo PPP	S5D9*, S7G2*
nxd_smtp_client	NetX Duo SMTP Client	S5D9*, S7G2
nxd_snmp	NetX Duo SNMP	S5D3*, S5D5*, S5D9*, S7G2
nxd_snmp_client	NetX Duo SNMP Client	S5D9*, S7G2
nxd_telnet_client	NetX Duo Telnet Client	S5D9*, S7G2
nxd_telnet_server	NetX Duo Telnet Server	S5D9*, S7G2
nxd_tftp_client	NetX Duo TFTP Client	S5D9*, S7G2
nxd_tftp_server	NetX Duo TFTP Server	S5D9*, S7G2

Module Name	SSP Feature	Supported Synergy MCU Groups
nxd_mqtt_client	NetX Duo MQTT Client	S5D3, S5D5, S5D9, S7G2
nxd_tls_secure	NetX Duo TLS Secure	S5D3, S5D5, S5D9, S7G2
nxd_web_http_client	NetX Duo Web HTTP1.1 Client	S5D5*, S5D9, S7G2
	NetX Duo Web HTTPS Client	S5D5, S5D9, S7G2
nxd_web_http_server	NetX Duo Web HTTP1.1 Server	S5D9, S7G2
	NetX Duo Web HTTPS Server	S5D9, S7G2
Tx	ThreadX	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
Lx_nor	LevelX NOR	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
ux_device_class_storage	USBX Device Class Mass Storage	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
ux_device_class_hid	USBX Device Class HID	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
ux_device_class_cdc_acm	USBX Device Class CDC-ACM	S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2
ux_host_class_cdc_acm	USBX Host Class CDC-ACM	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
ux_host_class_hid	USBX Host Class HID	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
ux_host_class_hub	USBX Host HUB	S5D3, S5D5, S5D9, S7G2
ux_host_class_printer	USBX Host Class Printer	S3A3, S3A7, S5D9, S7G2
ux_host_class_storage	USBX Host Class Mass Storage	S3A1, S3A3, S3A7, S5D3, S5D5, S5D9, S7G2
ux_host_class_video	USBX Host Video class	S5D9, S7G2

* NetX and NetX Duo Applications are MCU-independent application layer protocols dependent on the NetX and Ethernet drivers. All MCUs on which NetX has been tested and verified support these protocols.

8.4 Cryptographic Functions for Each MCU Supported in this Release

Function	S5D3, S5D5, S5D9, S7G2	S3A1, S3A3, S3A6, S3A7	S124, S128, S1JA
TRNG	Generate and read random number	Generate and read random number	Generate and read random number
AES	Encryption, decryption, Key Generation - wrapped keys	Encryption, decryption, Key Generation - wrapped keys	Encryption, decryption
AES Key Size	128-bit, 192-bit, 256-bit	128-bit, 256-bit	128-bit, 256-bit
AES Key Type	Plain text / raw key, wrapped key	Plain text / raw key, wrapped key	Plain text / raw key
AES Chaining Modes	ECB, CBC, CTR, GCM, XTS ^{††}	ECB, CBC, CTR, GCM, XTS	ECB, CBC, CTR
ARC4	Encryption, decryption	NA	NA
TDES	Encryption, decryption	NA	NA
TDES Key Size	192-bit	NA	NA
TDES Chaining Modes	ECB, CBC, CTR	NA	NA
RSA	Signature Generation, Signature Verification, Public-key Encryption, Private-key Decryption,	NA	NA

Function	S5D3, S5D5, S5D9, S7G2	S3A1, S3A3, S3A6, S3A7	S124, S128, S1JA
	Key Generation - plain text and wrapped keys		
RSA Key Size	1024-bit, 2048-bit	NA	NA
RSA Key Type	Plain text / raw key, Wrapped key	NA	NA
Key Installation	AES, ECC, RSA keys	AES keys	NA
ECC	Key Generation – plain text and wrapped keys, Scalar Multiplication, ECDSA – Signature Generation, ECDSA – Signature Verification	NA	NA
ECC Key Size (in bits)	192-bit, 224-bit, 256-bit, and 384-bit	NA	NA
ECC Key Type	Plain text / raw keys and wrapped keys	NA	NA
DSA	Signature Generation, Signature Verification	NA	NA
DSA Key Size	(1024, 160)-bit, (2048, 224)-bit, (2048, 256)-bit	NA	NA
HASH	SHA1, SHA224, SHA256, MD5	NA	NA

†† XTS is supported for 128-bit and 256-bit keys only.

8.5 Experimental Modules Supported in this Release

Modules that have not been tested on the MCUs have been classified as experimental modules and are listed in the following table. These experimental modules are currently not supported by Synergy Configuration tools and use of these modules in customer projects is not supported by Renesas at this time.

Experimental Modules		
Module Name	SSP Feature	Supported Synergy MCU Groups
ux_device_class_cdc_ecm	USBX Device Class CDC-ECM	S124, S3A3, S3A7, S5D9, S7G2
ux_device_class_rndis	USBX Device Class RNDIS	S124, S3A3, S3A7, S5D9, S7G2
ux_host_class_gser	USBX Host Class Generic Serial	S3A3, S3A7, S5D9, S7G2
ux_host_class_prolific	USBX Host Class Prolific	S3A3, S3A7, S5D9, S7G2
ux_host_class_swar	USBX Host Class Swar	S3A3, S3A7, S5D9, S7G2
ux_network_driver	USBX Network Driver	S124, S3A3, S3A7, S5D9, S7G2

9. Additional Technical Notes

- Subscribe to the Synergy Technical Bulletin Board to receive the latest technical news and notifications about new features, known issues, workarounds, and release announcements. To subscribe, visit www.renesasrulz.com/synergy/synergy_tech_notes/f/214.aspx. Sign in to Renesas Rulz, and press **Email Subscribe to this forum**.
- Additional technical information, including informative papers and articles on SSP and Synergy can be found at Synergy Knowledge Base, www.renesas.com/synergy/knowledgebase.

Website and Support

Visit the following vanity URLs to learn about key elements of the Synergy Platform, download components and related documentation, and get support.

Synergy Software	www.renesas.com/synergy/software
Synergy Software Package	www.renesas.com/synergy/ssp
Software add-ons	www.renesas.com/synergy/addons
Software glossary	www.renesas.com/synergy/softwareglossary
Development tools	www.renesas.com/synergy/tools
Synergy Hardware	www.renesas.com/synergy/hardware
Microcontrollers	www.renesas.com/synergy/mcus
MCU glossary	www.renesas.com/synergy/mcuglossary
Parametric search	www.renesas.com/synergy/parametric
Kits	www.renesas.com/synergy/kits
Synergy Solutions Gallery	www.renesas.com/synergy/solutionsgallery
Partner projects	www.renesas.com/synergy/partnerprojects
Application projects	www.renesas.com/synergy/applicationprojects
Self-service support resources:	
Documentation	www.renesas.com/synergy/docs
Knowledgebase	www.renesas.com/synergy/knowledgebase
Forums	www.renesas.com/synergy/forum
Training	www.renesas.com/synergy/training
Videos	www.renesas.com/synergy/videos
Chat and web ticket	www.renesas.com/synergy/resourcelibrary

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	May 29.20	-	First release
1.01	Jun.16.20	-	Second release

SSP v1.7.8 Release Note

Publication Date: Jun.16.20

Published by: Renesas Electronics Corporation
